

➤ NOTICE REGARDING A TEMPORARY PRODUCT CHANGE

PLEASE NOTE:

Due to supply chain issues, the following part numbers will have the modified reservoir fitting pictured below until further notice:

CX-3000S

CX-3001S

CX-3100S

CX-3101S

CX-3103S

CX-3104S

CX-3105S



ORIGINAL RESERVOIR FITTING



MODIFIED/TEMPORARY RESERVOIR FITTING

Please note that the modified reservoir was thoroughly tested for performance and is subject to our standard quality promises. This change is a result of supply chain challenges and an effort to continue providing the products researchers need to perform important work. The design will revert to the original fitting as soon as possible.

Please contact us with any questions or concerns at invivo@basinc.com.